

TECHNICAL INFORMATION BULLETIN

Subject: Receivers That Support the DISH Pro Plus (DP Plus) 44 Switch

This bulletin updates and replaces Technical Information Bulletin #131830. The change reflects software releases for the DISH 301 and DISH Player-DVR 921 receivers.

DISH Network recently released the DP Plus 44 switch with power inserter (Part Number 129349) and DP Plus Separator (Part Number 123254). Below is a list of receivers and corresponding software versions that support this product:

DP Plus dual-tuner receivers

4 satellite location support AND
Single-cable support with DP Plus Separator

Receiver Model	Software Version
DISH 322	L152 & later
DISH Player-DVR 522	L162 & later
DISH 721	L171 & later
DISH Player-DVR 921	L186 & later

Legacy receiver with SuperDISH 105° W / 121° W support

4 satellite location support

Receiver Model	Software Version
2700/2800/3700	795P & later
3800/3900	P230 & later
4700/4900	P215 & later
6000	780P & later

DISH Pro single-tuner receivers

4 satellite locations support

Receiver Model	Software Version
DISH 111	P270 & later
DISH 301	P201, P226 & later
DISH 311	P254 & later
DISH 501/508 DISH Player-DVR 510	P221 & later
DISH 811	P266 & later

Legacy receivers *without* SuperDISH 105° W / 121° W support

3 DBS satellite location support

Receiver Model	Software Version
1000	800P & later
2000	712P & later
3000	806P & later
4000	811P & later
5000	815P & later
7100/7200	123P & later; WebClient 16917 & later
JVC-HMDSR100	820P & later

Note: DISH Network receivers do not support installations where both the 61.5° and 148° satellite locations are provided to the satellite receiver.